


SAND SILOS – PAESEN CONCRETE FACTORY – BELGIUM

Photos of 3 sand silos for the **PAESEN** concrete factory, in Houthalen (B) taken in April 2006. The silos were sandblasted and coated with **ZINGA** then top coated with a PU with a mist and full coat technique by the Construction and Application company **ELLIMETAL** in Meeuwen (B).



System:

ZINGA	1 x 80 µm DFT
2c PU Topcoat	1 x 70 µm DFT mist coat/full coat



PU mist coat




PU full coat



Final condition in 2006

17 years after the original application, i.e. on 11-09-2023, two representatives of **ZINGAMETALL Belgium** made an inspection on site. Their conclusion was that the 3 silos were still in **perfect condition**, but with some mechanical damages on the lower part of the silos.

Please look at the 2 below photos taken in 2023,



while the 2 silos on the left, not coated with **ZINGA**, are in less good condition !

